



IPC/WHMA-A-620D



Requirements and Acceptance for Cable and Wire Harness Assemblies

If a conflict occurs between the English and translated versions of this document, the English version will take precedence.

Developed by the IPC Task Group (7-31f) of the Product Assurance Subcommittee (7-30) and the WHMA Industry Technical Guidelines Committee (ITGC)

Supersedes:

IPC/WHMA-A-620C -
January 2017
IPC/WHMA-A-620B with
Amendment 1 -
August 2013
IPC/WHMA-A-620B -
October 2012
IPC/WHMA-A-620A -
July 2006
IPC/WHMA-A-620 -
January 2002

Users of this publication are encouraged to participate in the development of future revisions.

Contact:

IPC

Wiring Harness Manufacturers Assoc.
(An affiliate of IPC)

Table of Contents

1 General	1-1	1.13 Facilities	1-6
1.1 Scope	1-1	1.13.1 Field Assembly Operations	1-6
1.2 Purpose	1-1	1.13.2 Health and Safety	1-6
1.3 Classification	1-1	1.14 Electrostatic Discharge (ESD) Protection	1-6
1.4 Measurement Units and Applications	1-1	1.15 Tools and Equipment	1-7
1.4.1 Verification of Dimensions	1-1	1.15.1 Control	1-7
1.5 Definition of Requirements	1-1	1.15.2 Calibration	1-7
1.5.1 Inspection Conditions	1-2	1.16 Materials and Processes	1-7
1.5.1.1 Acceptable	1-2	1.17 Electrical Clearance	1-8
1.5.1.2 Defect	1-2	1.18 Contamination	1-8
1.5.1.2.1 Disposition	1-2	1.19 Rework/Repair	1-8
1.5.1.3 Process Indicator	1-2	1.19.1 Rework	1-8
1.5.1.4 Combined Conditions	1-3	1.19.2 Repair	1-8
1.5.1.5 Conditions Not Specified	1-3	1.19.3 Post Rework/Repair Cleaning	1-8
1.5.1.6 Uncommon or Specialized Designs	1-3	2 Applicable Documents	2-1
1.5.2 Material and Process Nonconformance	1-3	2.1 IEC	2-1
1.6 Process Control	1-3	2.2 Joint Industry Standards	2-1
1.6.1 Statistical Process Control	1-3	2.3 Society of Automotive Engineers (SAE)	2-1
1.7 Order of Precedence	1-4	2.4 American National Standards Institute (ANSI)	2-1
1.7.1 Clause References	1-4	2.5 International Organization for Standardization (ISO)	2-1
1.7.2 Appendices	1-4	2.6 ESD Association (ESDA)	2-2
1.8 Terms and Definitions	1-4	2.7 United States Department of Defense (DoD)	2-2
1.8.1 FOD (Foreign Object Debris)	1-4	2.8 International Electrotechnical Commission (IEC)	2-2
1.8.2 Inspection	1-4	2.9 Aerospace Industries Association (AIA/NAS)	2-2
1.8.3 Manufacturer (Assembler)	1-4	2.10 Electronics Industries Alliance	2-2
1.8.4 Objective Evidence	1-4	2.11 ASTM International	2-2
1.8.5 Process Control	1-4	2.12 Institute of Electrical and Electronics Engineers	2-2
1.8.6 Supplier	1-4	3 Preparation	3-1
1.8.7 User	1-5	3.1 Stripping	3-2
1.8.8 Wire Diameter (AWG)	1-5	3.2 Strand Damage and End Cuts	3-2
1.8.9 Engineering Documentation	1-5	3.3 Conductor Deformation/Birdcaging	3-5
1.9 Requirements Flow Down	1-5		
1.10 Personnel Proficiency	1-5		
1.11 Acceptance Requirements	1-5		
1.12 Inspection Methodology	1-5		
1.12.1 Process Verification Inspection	1-5		
1.12.2 Visual Inspection	1-5		
1.12.2.1 Lighting	1-5		
1.12.2.2 Magnification Aids	1-5		

Table of Contents (cont.)

3.4 Twisting of Wires	3-7	4.8.3.2 Solder	4-34
3.5 Insulation Damage – Stripping	3-8	4.8.4 Pierced/Perforated/Punched	4-35
4 Soldered Terminations	4-1	4.8.4.1 Lead/Wire Placement	4-35
4.1 Material, Components and Equipment	4-2	4.8.4.2 Solder	4-37
4.1.1 Materials	4-2	4.8.5 Hook	4-38
4.1.1.1 Solder	4-2	4.8.5.1 Lead/Wire Placement	4-38
4.1.1.1.1 Solder Purity Maintenance	4-3	4.8.5.2 Solder	4-40
4.1.1.2 Flux	4-4	4.8.6 Cup	4-41
4.1.1.3 Adhesives	4-4	4.8.6.1 Lead/Wire Placement	4-41
4.1.1.4 Solderability	4-5	4.8.6.2 Solder	4-42
4.1.1.5 Tools and Equipment	4-5	4.8.7 Series Connected	4-44
4.1.2 Gold Removal	4-5	4.8.8 Lead/Wire Placement – AWG 30 and Smaller Diameter Wires	4-45
4.2 Cleanliness	4-6	5 Crimp Terminations (Contact and Lugs)	5-1
4.2.1 Presoldering	4-6	5.1 Stamped and Formed – Open Barrel	5-3
4.2.2 Postsoldering	4-6	5.1.1 Insulation Support	5-4
4.2.2.1 Foreign Object Debris (FOD)	4-6	5.1.1.1 Inspection Window	5-4
4.2.2.2 Flux Residue	4-7	5.1.1.2 Crimp	5-6
4.2.2.2.1 Cleaning Required	4-7	5.1.2 Insulation Clearance if No Support Crimp	5-8
4.2.2.2.2 No-Clean Process	4-7	5.1.3 Conductor Crimp	5-9
4.3 Solder Connection	4-8	5.1.4 Crimp Bellmouth	5-11
4.3.1 General Requirements	4-10	5.1.5 Conductor Brush	5-13
4.3.2 Soldering Anomalies	4-11	5.1.6 Carrier Cutoff Tab	5-15
4.3.2.1 Exposed Basis Metal	4-11	5.1.7 Individual Wire Seal	5-16
4.3.2.2 Partially Visible or Hidden Solder Connections	4-11	5.2 Stamped and Formed – Closed Barrel	5-18
4.4 Wire/Lead Preparation, Tinning	4-12	5.2.1 Insulation Clearance	5-19
4.5 Wire Insulation	4-14	5.2.2 Insulation Support Crimp	5-20
4.5.1 Clearance	4-14	5.2.3 Conductor Crimp and Bellmouth	5-21
4.5.2 Postsolder Damage	4-16	5.2.4 Cutoff Tabs	5-23
4.6 Insulation Sleeving	4-17	5.3 Machined Contacts	5-24
4.7 Soldered Strand Separation (Birdcaging)	4-19	5.3.1 Insulation Clearance	5-24
4.8 Terminals	4-20	5.3.2 Insulation Support Style	5-26
4.8.1 Turrets and Straight Pins	4-23	5.3.3 Conductor	5-27
4.8.1.1 Lead/Wire Placement	4-23	5.3.4 Crimping	5-29
4.8.1.2 Solder	4-25	5.3.5 CMA Buildup	5-31
4.8.2 Bifurcated	4-26	5.4 Termination Ferrule Crimp	5-33
4.8.2.1 Lead/Wire Placement – Side Route	4-26	5.5 Shrink Sleeving – Wire Support – Crimped Terminals	5-35
4.8.2.2 Lead/Wire Placement – Bottom and Top Route	4-28	6 Insulation Displacement Connection (IDC)	6-1
4.8.2.3 Lead/Wire Placement – Staked/ Constrained Wires	4-30	6.1 Mass Termination, Flat Cable	6-2
4.8.2.4 Solder	4-31	6.1.1 End Cutting	6-2
4.8.3 Slotted	4-33	6.1.2 Notching	6-3
4.8.3.1 Lead/Wire Placement	4-33	6.1.3 Planar Ground Plane Removal	6-4
		6.1.4 Connector Position	6-5
		6.1.5 Connector Skew and Lateral Position	6-8
		6.1.6 Retention	6-9

Table of Contents (cont.)

6.2 Discrete Wire Termination	6-10	9.4 Connector Damage	9-15
6.2.1 General	6-10	9.4.1 Criteria	9-15
6.2.2 Position of Wire	6-11	9.4.2 Limits – Hard Face – Mating Surface	9-16
6.2.3 Overhang (Extension)	6-12	9.4.3 Limits – Soft Face – Mating Surface or Rear Seal Area	9-17
6.2.4 Insulation Crimp	6-13	9.4.4 Contacts	9-18
6.2.5 Damage in Connection Area	6-15	9.5 Installation of Contacts and Sealing Plugs into Connectors	9-19
6.2.6 End Connectors	6-16	9.5.1 Installation of Contacts	9-19
6.2.7 Pass Through Connectors	6-17	9.5.2 Installation of Sealing Plugs	9-21
6.2.8 Wiremount Connectors	6-18	10 Over-Molding/Potting	10-1
6.2.9 Subminiature D-Connector (Series Bus Connector)	6-19	10.1 Over-Molding	10-4
6.2.10 Modular Connectors (RJ Type)	6-21	10.1.1 Mold Fill	10-4
7 Ultrasonic Welding	7-1	10.1.1.1 Inner	10-4
7.1 Insulation Clearance	7-2	10.1.1.2 Outer	10-7
7.2 Weld Nugget	7-3	10.1.1.2.1 Mismatch	10-10
8 Splices	8-1	10.1.1.2.2 Fit	10-11
8.1 Soldered Splices	8-2	10.1.1.2.3 Cracks, Flow Lines, Chill Marks (Kink Lines) or Weld Lines	10-14
8.1.1 Mesh	8-3	10.1.1.2.4 Color	10-16
8.1.2 Wrap	8-5	10.1.2 Blow Through	10-17
8.1.3 Hook	8-7	10.1.3 Position	10-18
8.1.4 Lap	8-8	10.1.4 Flashing	10-21
8.1.4.1 Two or More Conductors	8-9	10.1.5 Wire Insulation, Jacket or Sleeving Damage	10-23
8.1.4.2 Insulation Opening (Window)	8-12	10.1.6 Curing	10-24
8.1.5 Heat Shrinkable Solder Devices	8-13	10.2 Potting (Thermoset Molding)	10-25
8.2 Crimped Splices	8-15	10.2.1 Filling	10-25
8.2.1 Barrel	8-15	10.2.2 Fit to Wire or Cable	10-29
8.2.2 Double Sided	8-18	10.2.3 Curing	10-31
8.2.3 Contact	8-21	10.3 Over-Molding of Flexible Flat Ribbon	10-32
8.2.4 Wire In-Line Junction Devices (Cliffy Junctions)	8-23	10.3.1 Mounting and Alignment Feature Adhesion	10-35
8.3 Ultrasonic Weld Splices	8-24	10.3.2 Adhesion Between Ribbon and Connector Potting	10-36
9 Connectorization	9-1	10.3.3 Mounting Hardware	10-37
9.1 Hardware Mounting	9-2	11 Measuring Cable Assemblies and Wires	11-1
9.1.1 Jackpost – Height	9-2	11.1 Measuring – Cable and Wire Length Tolerance	11-2
9.1.2 Jackscrew – Protrusion	9-3	11.2 Measuring – Cable	11-2
9.1.3 Retaining Clips	9-4	11.2.1 Reference Surfaces – Straight/Axial Connectors	11-2
9.1.4 Connector Alignment	9-5	11.2.2 Reference Surfaces – Right-Angle Connectors	11-3
9.2 Strain Relief	9-6	11.2.3 Length	11-3
9.2.1 Clamp Fit	9-6	11.2.4 Breakout	11-4
9.2.2 Wire Dress	9-7		
9.2.2.1 Straight Approach	9-8		
9.2.2.2 Side Approach	9-9		
9.3 Sleeving and Boots	9-10		
9.3.1 Position	9-10		
9.3.2 Bonding	9-11		

Table of Contents (cont.)

11.2.4.1 Breakout Measurement Points	11-4	13.9 Center Pin	13-20
11.2.4.2 Breakout Length	11-5	13.9.1 Position	13-20
11.3 Measuring – Wire	11-6	13.9.2 Damage	13-21
11.3.1 Electrical Terminal Reference Location	11-6	13.10 Semirigid Coax	13-22
11.3.2 Length	11-7	13.10.1 Bending and Deformation	13-22
12 Marking/Labeling	12-1	13.10.2 Surface Condition	13-25
12.1 Content	12-2	13.10.2.1 Solid	13-25
12.2 Legibility	12-2	13.10.2.2 Conformable Cable	13-27
12.3 Permanency	12-4	13.10.3 Dielectric Cutoff	13-28
12.4 Location and Orientation	12-5	13.10.4 Dielectric Cleanliness	13-30
12.5 Functionality	12-6	13.10.5 Center Conductor Pin	13-31
12.6 Marker Sleeve	12-7	13.10.5.1 Point	13-32
12.6.1 Wrap Around	12-7	13.10.5.2 Damage	13-34
12.6.2 Tubular	12-9	13.10.6 Solder	13-34
12.7 Flag Markers	12-10	13.11 Swage-Type Connector	13-36
12.7.1 Adhesive	12-10	13.12 Soldering and Soldering of Biaxial/ Multi-Axial Shielded Wire	13-37
12.8 Tie Wrap Markers	12-10	13.12.1 Jacket Strip Installation	13-37
13 Coaxial and Biaxial Cable Assemblies	13-1	13.12.2 Ring Installation	13-39
13.1 Stripping	13-2	14 Security	14-1
13.2 Center Conductor Termination	13-4	14.1 Tie Wrap/Lacing Application	14-2
13.2.1 Crimp	13-4	14.1.1 Tightness	14-7
13.2.2 Solder	13-6	14.1.2 Damage	14-8
13.3 Solder Ferrule Pins	13-8	14.1.3 Spacing	14-8
13.3.1 General	13-8	14.2 Breakouts	14-9
13.3.2 Insulation	13-10	14.2.1 Individual Wires	14-9
13.4 Coaxial Connector – Printed Wire Board Mount	13-11	14.2.2 Spacing	14-10
13.5 Coaxial Connector – Center Conductor Length – Right Angle Connector	13-12	14.3 Routing	14-13
13.6 Coaxial Connector – Center Conductor Solder	13-13	14.3.1 Wire Crossover	14-13
13.7 Coaxial Connector – Terminal Cover	13-15	14.3.2 Bend Radius	14-14
13.7.1 Soldering	13-15	14.3.3 Coaxial Cable	14-15
13.7.2 Press Fit	13-16	14.3.4 Unused Wire Termination	14-16
13.8 Shield Termination	13-17	14.3.4.1 Shrink Sleeving	14-16
13.8.1 Clamped Ground Rings	13-17	14.3.4.2 Flexible Sleeving	14-17
13.8.2 Crimped Ferrule	13-18	14.3.5 Ties over Splices and Ferrules	14-17
		14.4 Broom Stitching	14-18
		15 Harness/Cable Electrical Shielding	15-1
		15.1 Braided	15-2
		15.1.1 Direct Applied	15-3
		15.1.2 Prewoven	15-5
		15.2 Shield Termination	15-6
		15.2.1 Shield Jumper Wire	15-6
		15.2.1.1 Attached Lead	15-6

Table of Contents (cont.)

15.2.1.1.1 Solder	15-7	17.3 Wire/Harness Installation	17-15
15.2.1.1.2 Crimp	15-11	17.3.1 Stress Relief	17-15
15.2.1.2 Shield Braid	15-12	17.3.2 Wire Dress	17-16
15.2.1.2.1 Woven	15-12	17.3.3 Service Loops	17-17
15.2.1.2.2 Combed and Twisted	15-12	17.3.4 Clamping	17-16
15.2.1.3 Daisy Chain	15-13	17.3.5 Tie Wrap Lacing	17-18
15.2.1.4 Common Ground Point	15-13	17.3.6 Raceways	17-19
15.2.2 No Shield Jumper Wire	15-14	17.3.7 Grommets	17-20
15.2.2.1 Shield Not Folded Back	15-14	17.3.7.1 Wire/Cable/Bundle Sealing Not Required ..	17-20
15.2.2.2 Shield Folded Back	15-15	17.3.7.1.1 Wire/Cable Sealing Required ..	17-21
15.3 Shield Termination – Connector	15-16	18 Solderless Wrap	18-1
15.3.1 Shrink	15-16	19 Testing	19-1
15.3.2 Crimp	15-18	19.1 Nondestructive Test	19-2
15.3.3 Shield Jumper Wire Attachment	15-20	19.2 Testing After Rework or Repair	19-2
15.3.4 Soldered	15-21	19.3 Interconnect Table Usage	19-2
15.4 Shield Termination – Splicing Prewoven	15-21	19.4 Mechanical Test	19-3
15.4.1 Soldered	15-22	19.4.1 Selection	19-3
15.4.2 Tie/Tape On	15-24	19.5 Electrical Test Methods	19-4
15.5 Tapes – Barrier and Conductive, Adhesive or Nonadhesive	15-25	19.5.1 Continuity	19-4
15.6 Conduit (Shielding)	15-26	19.5.2 Shorts	19-5
15.7 Shrink Tubing – Conductive Lined	15-27	19.5.3 Dielectric Withstanding Voltage (DWW)	19-6
16 Cable/Wire Harness Protective Coverings	16-1	19.5.4 Insulation Resistance (IR)	19-7
16.1 Braid	16-2	19.5.5 Voltage Standing Wave Ratio (VSWR)	19-8
16.1.1 Direct Applied	16-2	19.5.6 Insertion Loss	19-8
16.1.2 Prewoven	16-4	19.5.7 Reflection Coefficient	19-9
16.2 Sleeving/Shrink Tubing	16-6	19.5.8 User Defined	19-9
16.2.1 Sealant	16-7	19.6 Mechanical Test	19-10
16.3 Spiral Plastic Wrap (Spiral Wrap Sleeving)	16-8	19.6.1 Selection	19-10
16.4 Wire Loom Tubing – Split and Unsplit	16-9	19.7 Mechanical Test Methods	19-11
16.5 Tapes, Adhesive and Nonadhesive	16-9	19.7.1 Crimp Height (Dimensional Analysis)	19-11
17 Finished Assembly Installation	17-1	19.7.1.1 Terminal Positioning	19-12
17.1 General	17-2	19.7.2 Pull Force (Tensile)	19-13
17.2 Hardware Installation	17-3	19.7.2.1 Without Documented Process Control	19-14
17.2.1 Threaded Fasteners	17-4	19.7.3 Crimp Force Monitoring	19-18
17.2.1.1 Minimum Torque	17-6	19.7.4 Crimp Tool Qualification	19-18
17.2.2 Wires	17-8	19.7.5 Contact Retention Verification	19-18
17.2.2.1 Solid Wires	17-9	19.7.6 RF Connector Shield Pull Force (Tensile) ...	19-19
17.2.2.2 Stranded Wires	17-11	19.7.7 RF Connector Shield Ferrule Torsion	19-20
17.2.3 Safety Wiring	17-12	19.7.8 User Defined	19-20
17.2.4 Safety Cable	17-14	20 High Voltage Applications	20-1

Table of Contents (cont.)

Appendix A	Terms and Definitions	A-1	Table 13-2	Semirigid Coax Deformation	13-24
Appendix B	Reproducible Test Tables	B-1	Table 13-3	Dielectric Cutoff	13-28
Appendix C	Guidelines for Soldering Tools and Equipment	C-1	Table 14-1	Minimum Bend Radius Requirements	14-14
Table A-1	Electrical Clearance	A-5	Table 17-1	Minimum Swaged Ferrule Pull-Off Load	17-14
Table 1-1	Magnification Aid Applications – Wire and Wire Connections	1-6	Table 19-1	Electrical Test Requirements	19-3
Table 1-2	Magnification Aid Applications – Other	1-6	Table 19-2	Continuity Test Minimum Requirements	19-4
Table 3-1	Allowable Strand Damage	3-4	Table 19-3	Shorts Test (low voltage isolation) Minimum Requirements	19-5
Table 4-1	Maximum Limits of Solder Bath Contaminant	4-3	Table 19-4	Dielectric Withstanding Voltage Test (DWV) Minimum Requirements	19-6
Table 4-2	Solder Connection Anomalies	4-11	Table 19-5	Insulation Resistance (IR) Test Minimum Requirements	19-7
Table 4-3	Turret and Straight Pin Terminal Lead/Wire Placement	4-23	Table 19-6	Voltage Standing Wave Ratio (VSWR) Test Parameters	19-8
Table 4-4	Bifurcated Terminal Lead/Wire Placement – Side Route	4-26	Table 19-7	Insertion Loss Test Parameters	19-8
Table 4-5	Bifurcated Terminal Lead/Wire Placement – Bottom Route	4-28	Table 19-8	Reflection Coefficient Test Parameters	19-9
Table 4-6	Staking Requirements of Side Route Straight Through Connections – Bifurcated Terminals	4-30	Table 19-9	Mechanical Test Requirements	19-10
Table 4-7	Pierced/Perforated/Punched Terminal Lead/Wire Placement	4-35	Table 19-10	Crimp Height Testing	19-11
Table 4-8	Hook Terminal Lead/Wire Placement	4-38	Table 19-11	Pull Force Testing Minimum Requirements	19-14
Table 4-9	AWG 30 and Smaller Wire Wrap Requirements	4-45	Table 19-12	Pull Test Force Values	19-15
Table 10-1	Definitions of Molding/Potting Visual Anomalies	10-2	Table 19-13	Pull Test Force Values (Classes 1 & 2) For UL, SAE, GM and Volvo	19-16
Table 11-1	Cable/Wire Length Measurement Tolerance	11-2	Table 19-14	Pull Test Force Values (Classes 1 & 2) For IEC	19-17
Table 13-1	Uniaxial and Biaxial Shield and Center Conductor Damage	13-2	Table 19-15	RF Connector Shield Pull Force Testing	19-19

1 General

1 General

1.1 Scope This standard prescribes practices and requirements for the manufacture of cable, wire and harness assemblies. This standard does not provide criteria for cross-section or X-ray evaluation.

If a conflict occurs between the English and translated versions of this document, the English version will take precedence.

The illustrations in this document portray specific points noted in the title of each section. A brief description follows each illustration. The development committee recognizes that different parts of the industry have different definitions for some terms used herein. For the purposes of this document, the terms cable and wire harness are used interchangeably.

IPC/WHMA-A-620 can be used as a stand-alone document for purchasing products, however it does not specify frequency of in-process inspection or frequency of end product inspection. No limit is placed on the number of process indicators or the number of allowable repair/rework of defects. Such information should be developed with a statistical process control plan (see IPC-9191).

1.2 Purpose This standard describes materials, methods, tests and acceptability criteria for producing crimped, mechanically secured, or soldered interconnections and the related assembly activities associated with cable and harness assemblies.

The intent of this document is to rely on process control methodology to ensure consistent quality levels during the manufacture of products.

Any method that produces an assembly conforming to the acceptability requirements described in this standard may be used.

Standards may be updated at any time, including with the use of amendments. The use of an amendment or newer revision is not automatically required. The revision in effect **shall [D1D2D3]** be as specified by the User.

1.3 Classification Use of this standard requires agreement on the Class to which the product belongs. The User has the ultimate responsibility for identifying the Class to which the assembly is evaluated. If the User does not establish and document the acceptance Class, the Manufacturer may do so. Criteria defined in this standard reflect three Product Classes, which are as follows:

Class 1 General Electronic Products

Includes products suitable for applications where the major requirement is the function of the completed assembly.

Class 2 Dedicated Service Electronic Products

Includes products where continued performance and extended life is required, and for which uninterrupted service is desired but not critical. Typically, the end-use environment would not cause failures.

Class 3 High Performance/Harsh Environment Electronic Products

Includes products where continued performance or performance-on-demand is critical, equipment downtime cannot be tolerated, end-use environment may be commonly harsh, and the equipment must function when required, such as life support systems and other critical systems.

1.4 Measurement Units and Applications This document uses the International System of Units (SI) in accordance with ASTM SI10-10, IEEE/ASTM SI 10, American National Standard for Metric Practice (Section 3). Imperial English equivalent units follow in brackets. The derived SI units used in this document are millimeters (mm) [in] for dimensions and dimensional tolerances, Celsius (°C) [°F] for temperature and temperature tolerances, grams (g) [oz] for weight, and lux (lx) [footcandles] for illuminance.

1.4.1 Verification of Dimensions Where not specifically invoked by this standard, actual measurements, e.g., of specific solder fillet dimensions, determination of damage and wrap percentages, are not required except for referee purposes.

1.5 Definition of Requirements The word “shall” is used in the text of this document wherever there is a requirement for materials, process or acceptance of cable, wire and harness assemblies.

Where the word **shall** indicates a requirement for at least one Class, the requirements for each Class are in brackets next to the **shall** requirement.