



API/EI Research Report 545-A

Verification of lightning protection requirements for above ground hydrocarbon storage tanks

First edition, October 2009

Currently in preview, click buy full version

Currently in preview, click buy full version

API/EI Research Report 545-A

Verification of lightning protection requirements for above ground
hydrocarbon storage tanks

First edition

October 2003

Published jointly by

API
and

ENERGY INSTITUTE LONDON

The Energy Institute is a professional membership body incorporated by Royal Charter 2003

Registered charity number 1097899

Copyright © 2009 by API, and
The Energy Institute, London:
The Energy Institute is a professional membership body incorporated by Royal Charter 2003.
Registered charity number 1097899, England
All rights reserved.

No part of this book may be reproduced by any means, or transmitted or translated into a machine language without the written permission of the publisher.

ISBN 978 0 85293 376 3

Published by the Energy Institute

The information contained in this publication is provided as guidance only and while every reasonable care has been taken to ensure the accuracy of its content, the Energy Institute cannot accept any responsibility for any action taken, or not taken, on the basis of this information. The Energy Institute shall not be liable to any person for any loss or damage which may arise from the use of any of the information contained in any of its publications.

Further copies can be obtained from:
Portland Customer Services, Commerce Way, Whitehall Industrial Estate, Colchester, CO2 8HP, UK.
t: +44 (0) 1206 796 551 e: sales@portland-services.com

or

Global Engineering Documents at (800) 854-7179 or (303) 397-7956
w: www.global.ihs.com

Electronic access to EI publications is available via our website, www.energyinstpubs.org.uk.
Documents can be purchased online as downloadable pdfs or on an annual subscription for single users and companies.
For more information, contact the EI Publications Team e: pubs@energyinst.org

CONTENTS OVERVIEW

	Page
Legal notices and disclaimers.....	iv
Foreword	v
 PHASE 1	
Acknowledgements	i
Executive summary.....	ii
Cul/LT-0234	
Review of lightning phenomena and the interaction with above ground storage tanks ..	1
Cul/LT-0235	
Review of tank base earthing and test current recommendations.....	43
EI-EN2-04	
Lightning tests to tank shell/shunt samples.....	55
EI-Vis1-01	
Visit to oil refinery A	73
EI-Vis2-02	
Visit to oil refinery B.....	83
EI-TN1-03	
Review of burn-through and hot-spot effects on metallic tank skins from lightning strikes ..	93
 PHASE 2	
Acknowledgment	i
Executive Summary	ii
Cul/LT-05-03 Lightning simulation testing to determine the required characteristics for roof bonding cables on external floating roof above ground storage tanks.....	1
Cul/LT-0401 Investigative tests on the lightning protection of submerged shunts with parallel roof bonding cables	31

LEGAL NOTICES AND DISCLAIMERS

The information contained in this publication is provided as guidance only, and although every effort has been made by API and EI to assure the accuracy and reliability of its contents, API and EI MAKE NO GUARANTEE THAT THE INFORMATION HEREIN IS COMPLETE OR ERROR-FREE. ANY PERSON OR ENTITY MAKING ANY USE OF THE INFORMATION HEREIN DOES SO AT HIS/HER/ITS OWN RISK. TO THE MAXIMUM EXTENT PERMITTED BY APPLICABLE LAW, THE INFORMATION HEREIN IS PROVIDED WITHOUT, AND API AND EI HEREBY EXPRESSLY DISCLAIM, ANY REPRESENTATION OR WARRANTY OF ANY KIND, WHETHER EXPRESS, IMPLIED OR STATUTORY, INCLUDING, WITHOUT LIMITATION, WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE AND NON-INFRINGEMENT. IN NO EVENT SHALL API OR EI BE LIABLE TO ANY PERSON, OR ENTITY USING OR RECEIVING THE INFORMATION HEREIN FOR ANY CONSEQUENTIAL, INCIDENTAL, PUNITIVE, INDIRECT OR SPECIAL DAMAGES (INCLUDING, WITHOUT LIMITATION, LOST PROFITS), REGARDLESS OF THE BASIS OF SUCH LIABILITY, AND REGARDLESS OF WHETHER OR NOT API OR EI HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES OR IF SUCH DAMAGES COULD HAVE BEEN FORESEEN.

The contents of this publication are not intended or designed to define or create legal rights or obligations, or set a legal standard of care.

API or EI is not undertaking to meet the duties of manufacturers, purchasers, users and/or employers to warn and equip their employees and others concerning safety risks and precautions, nor is API or EI undertaking any of the duties of manufacturers, purchasers, users and/or employers under local and regional laws and regulations. This information should not be used without first securing competent advice with respect to its suitability for any general or specific application, and all entities have an independent obligation to ascertain that their actions and practices are appropriate and suitable for each particular situation and to consult all applicable federal, state and local laws.

API AND EI HEREBY EXPRESSLY DISCLAIM ANY LIABILITY OR RESPONSIBILITY FOR LOSS OR DAMAGE RESULTING FROM THE VIOLATION OF ANY FEDERAL OR REGIONAL LAWS OR REGULATIONS WITH WHICH THIS PUBLICATION MAY CONFLICT.

Nothing contained in any API or EI publication is to be construed as granting any right, by implication or otherwise, for the manufacture, sale, or use of any method, apparatus, or product covered by letters patent. Neither should anything contained in the publication be construed as insuring anyone against liability for infringement of letters patent.

No reference made in this publication to any specific product or service constitutes or implies an endorsement, recommendation, or warranty thereof by API or EI.

API, EI, AND THEIR AFFILIATES, REPRESENTATIVES, CONSULTANTS, AND CONTRACTORS AND THEIR RESPECTIVE PARENTS, SUBSIDIARIES, AFFILIATES, CONSULTANTS, OFFICERS, DIRECTORS, EMPLOYEES, REPRESENTATIVES, AND MEMBERS SHALL HAVE NO LIABILITY WHATSOEVER FOR, AND SHALL BE HELD HARMLESS AGAINST, ANY LIABILITY FOR ANY INJURIES, LOSSES OR DAMAGES OF ANY KIND, INCLUDING DIRECT, INDIRECT, INCIDENTAL, CONSEQUENTIAL, OR PUNITIVE DAMAGES, TO PERSONS, INCLUDING PERSONAL INJURY OR DEATH, OR PROPERTY RESULTING IN WHOLE OR IN PART, DIRECTLY OR INDIRECTLY, FROM ACCEPTANCE, USE OR COMPLIANCE WITH THIS PUBLICATION.

FOREWORD

This publication has been produced at the request of the API RP 545 Task Force and the EI Electrical Committee.

It collates a number of research reports produced by Culham Electromagnetics and Lightning Limited (Culham) who were commissioned to investigate the lightning phenomena and the adequacy of lightning protection measures on above ground hydrocarbon storage tanks.

Currently international, British and United States standards contain requirements relating to lightning protection; however, these have not been verified through practical, scientific testing. As a result of the work commissioned by the API and EI, a new Recommended Practice (RP) is being developed which will incorporate the results of this investigation.

Suggested revisions are invited and should be submitted to the director of standards, API, 1220 L Street, N.W., Washington, D.C. 20005 or The Technical Department, Energy Institute, 61 New Cavendish Street, London, W1G 7AR.

Currently in preview, click buy full version

API/EI RESEARCH REPORT

VERIFICATION OF LIGHTNING PROTECTION REQUIREMENTS
FOR ABOVE GROUND HYDROCARBON STORAGE TANKS

PHASE 1

Currently in preview, click buy full version

Currently in preview, click buy full version

EXECUTIVE SUMMARY

CUL/LT-0234

REVIEW OF LIGHTNING PHENOMENA AND THE INTERACTION WITH ABOVE GROUND STORAGE TANKS

This document describes the phenomena of lightning, and how it is expected to interact with various types of tank designs, in particular with respect to the problems of hydrocarbon fires. It draws on the experience of refinery and tank farm visits by the author, including those reported in EI-Vis1-01 *Visit to oil refinery A* and EI-Vis2-02 *Visit to oil refinery B*, and other sources. The likely strike points on all types of tanks are described, and the current routes over tanks are shown for the fast and slow lightning components. The shunt/rim seal region for an open top FRT is shown to be the most susceptible to ignitions. Aluminium roof geodesic tanks appear to be the most likely type to suffer hot spots and burn through. The electrical properties of steel as a material for tanks is described along with descriptions of thermal and voltage sparking. Protection strategies for open FRTs, for roofed over tanks, and LPG tanks are described. Comments are made on the problems associated with petroleum product within the pontoons or on the surface of a floating roof. An analysis of the operation of the shunt/shell bonding cable suggests that it would play a vital part in suppressing sparking from the continuing current component of lightning, although it would play only a minor role in suppressing sparking from the fast component. The principal USA/UK lightning protection and oil industry documents are reviewed for their content on lightning protection of tanks.

CUL/LT-0235

REVIEW OF TANK BASE EARTHING AND TEST CURRENT RECOMMENDATIONS

The earthing of a storage tank may have important considerations for safety, and protection of instrumentation on the tank, but in practice the tank is likely to be intrinsically well earthed simply by its construction. Even so earthing rods should be (and are) generally used as recommended by international standards. Quality of earthing has little or no significance in storage tank fire protection. The document also discusses the likely currents which shunts may have to carry (up to 11 kA).

EI-EN2-04

LIGHTNING TESTS TO TANK SHELL/SHUNT SAMPLES

Tests at Culham replicated shunt/shell interfaces and subjected them to conducted lightning-type currents. Even clean steel shunt/shell interfaces sparked. Fast current components produce relatively small sparks, whereas long duration currents produce copious spark showers that are believed to be more hazardous. (In practice good protection against the latter currents can be achieved using a roof bonding cable.) Different shunt materials could also present less of a hazard. Currents in immersed shunts tended to cause an eruption of fluid, due to the arc pressure.

EI-VIS1-01
VISIT TO OIL REFINERY A

EI-VIS2-02
VISIT TO OIL REFINERY B

Describe the features seen during two visits to refineries. Some of the practical difficulties of providing and maintaining lightning protection in the field and over many years are observed and discussed, and some photographs are included.

EI-TN1-03
REVIEW OF BURN-THROUGH AND HOT-SPOT EFFECTS ON METALLIC TANK SKINS FROM LIGHTNING STRIKES

Discusses the threat of lightning strikes puncturing steel or aluminium tanks, or of causing internal hot-spots. Aluminium is easily punctured, and so geodesic roofs which use aluminium skins < 2 mm thick would be a hazard if they contained vapours within the flammable range. Steel skins 5 mm thick would not be expected to be punctured by a lightning attachment. Hot-spot hazards for such thick skins have not been investigated, but could be a hazard for severe strikes.

MAIN CONCLUSIONS AND RECOMMENDATIONS

1. Potential ignition hazards exist particularly at shunt/shell interfaces (for open top FRT) and geodesic roofs. The nature of the hydrocarbon, as well as temperature and ventilation, determines whether the vapour could be within a flammable range.
2. Sparking at shunts is inevitable, and is more severe for the long duration currents. Such sparks tend to fall downwards into the seal region, and any gaps between the seal and the shell would increase the likelihood of flammable vapour ignition. Therefore maintenance of the seal is important.
3. The severity of sparking can be significantly reduced, by using earth cables from the floating roof to the shell, or bonding via the ladder.
4. Immersed shunts should present a good solution to hazardous shunt sparking.

CUL/LT-0234

REVIEW OF LIGHTNING PHENOMENA AND THE INTERACTION WITH ABOVE GROUND STORAGE TANKS

CONTENTS

	Page
1 Introduction: The lightning phenomenon as relevant to above ground storage tanks . . .	3
1.1 General	3
1.2 Lightning strike rates to ground and isokeraunic levels	3
1.3 Electrical parameters of lightning	4
1.4 Lightning risk and protection principles.	6
1.5 The lightning cloud approach, induction charging, and space charges	6
1.6 Roof surface charging of tanks and bulk product charging	8
1.7 Attachment process to tanks and ground objects	8
2 The interaction of lightning with storage tanks	10
2.1 Floating roof tanks (FRT) and lightning induced fires	10
2.2 Discussion of lightning interaction with open top FRTs	13
2.3 Lightning interaction with other types of above ground storage tanks	13
2.4 Lightning interaction with geodesic lightweight roofs	14
2.5 Cone roof, or 'fixed roof' tanks.	15
2.6 Pressurised tanks for LPG	16
3 Lightning effects on materials: electrical heating and mechanical damage; burn through and hot-spots; thermal and voltage sparking	17
3.1 Effects due to lightning current flow through metallic conductors.	17
3.2 Effects at the lightning arc attachment point	17
3.3 Danger arising from sparking	18
4 Floating roof rim seals and the lightning induced fire problem	20
4.1 Introduction to sparking at seals	20
4.2 Floating roof seal types.	20
4.3 Discussion of sparking sources on seals and shunts.	22
4.4 Lightning risks to open FRTs from surface product and leaks into pontoons.	24
5 Lightning ignitions on roofed over floating roof tanks	26
5.1 Introduction to roofing of open top tanks.	26
5.2 Lightning hazards with roofed over tanks	26
6 Lightning hazards to cone roof (fixed roof) tanks	28
7 Lightning hazards to LPG tanks	30
8 Summary of lightning effects on above ground storage tanks	31
8.1 The lightning process	31
8.2 Effects on materials	32

8.3	Protection methods to prevent lightning induced rim seal fires	32
8.4	Protection of roofed over tanks.	33
8.5	Lightning effects on roof surface product, and product in pontoons	33
8.6	Lightning effects on cone roof tanks.	34
8.7	Lightning effects on pressurised LPG tanks	34
9	Conclusions and recommendations	35
10	References	36
Annexes:		
Annex A	Skin effect in steel sheets	37
Annex B	Review of documents	38
B.1	BS6651:1999 <i>Code of practice on protection of buildings against lightning</i>	38
B.2	API 545 <i>Recommended practice for lightning protection of above ground hydrocarbon storage tanks</i>	38
B.3	NFPA 780 <i>Standard for the installation of lightning protection systems</i> , 2000 Edition . . .	38
B.4	API 650 <i>Welded steel tanks for oil storage</i> 10th edition. Nov 98 with add 3.	39
B.5	EEMUA 159 <i>User's guide to the inspection, maintenance and repair of above ground vertical cylindrical steel storage tanks</i> , 3rd edition 2003	39
B.6	NFPA 30 <i>Flammable and combustible liquids code</i> 2003 edition	40
B.7	Review of information from Chicago bridge and iron.	40
Annex C	World isokeraunic levels	41
Figures:		
Figure 1	Ref 1013 Huffines and Orville American meteorological society lightning ground flash density and thunderstorm duration in the continental United States	3
Figure 2	Schematic diagrams of the high current and the 'continuing' current components of a lightning strike.	5
Figure 3	'Cone of protection' principle for lightning protection.	6
Figure 4	The process of attachment from a lightning cloud to a tank.	9
Figure 5a	Current routes for flash to top of shell.	11
Figure 5b	Current routes for flash to floating roof.	11
Figure 5c	Current routes for flash to ground near a floating roof tank	12
Figure 6	Open top floating roof tanks	12
Figure 7	Typical fixed (cone) roof tank with vent at the top	15
Figure 8	LPG tank, all steel, pressurised.	18
Figure 9	Effects at the arc attachment point	18
Figure 10	Typical floating roof pantograph type primary seal, with secondary seal, shunt and foam dam.	21
Figure A.1	Cross section of the top of the steel shell.	37
Tables:		
Table 1	Lightning flash parameters	5