

IEEE Recommended Practice for Quality Control Testing of External Discharges on Stator Coils, Bars, and Windings

IEEE Power and Energy Society

Sponsored by the
Electric Machinery Committee

IEEE
3 Park Avenue
New York, NY 10016-5997
USA

IEEE Std 1799™-2012

30 November 2012

Currently in preview, click buy full version

IEEE Recommended Practice for Quality Control Testing of External Discharges on Stator Coils, Bars, and Windings

Sponsor

**Electric Machinery Committee
of the
IEEE Power and Energy Society**

Approved 19 October 2012

IEEE-SA Standards Board

Abstract: The procedure for quality control testing of external discharges on stator coils, bars and windings of large air-cooled ac electric machines is described in this recommended practice.

Keywords: ac, corona-imaging instrument, discharge inception voltage, electrical insulation, external discharges, IEEE 1799, stator winding, ultraviolet radiation

The Institute of Electrical and Electronics Engineers, Inc.
3 Park Avenue, New York, NY 10016-5997, USA

Copyright © 2012 by The Institute of Electrical and Electronics Engineers, Inc.
All rights reserved. Published 30 November 2012. Printed in the United States of America.

IEEE is a registered trademark in the U.S. Patent & Trademark Office, owned by The Institute of Electrical and Electronics Engineers, Incorporated.

PDF: ISBN 978-0-7381-7593-5 STD97305
Print: ISBN 978-0-7381-7670-3 STDPD97305

IEEE prohibits discrimination, harassment, and bullying. For more information, visit <http://www.ieee.org/web/aboutus/whatis/policies/p9-26.html>.
No part of this publication may be reproduced in any form, in an electronic retrieval system or otherwise, without the prior written permission of the publisher.

Notice and Disclaimer of Liability Concerning the Use of IEEE Documents: IEEE Standards documents are developed within the IEEE Societies and the Standards Coordinating Committees of the IEEE Standards Association (IEEE-SA) Standards Board. IEEE develops its standards through a consensus development process, approved by the American National Standards Institute, which brings together volunteers representing varied viewpoints and interests to achieve the final product. Volunteers are not necessarily members of the Institute and serve without compensation. While IEEE administers the process and establishes rules to promote fairness in the consensus development process, IEEE does not independently evaluate, test, or verify the accuracy of any of the information or the soundness of any judgments contained in its standards.

Use of an IEEE Standard is wholly voluntary. IEEE disclaims liability for any personal injury, property or other damage, of any nature whatsoever, whether special, indirect, consequential, or compensatory, directly or indirectly resulting from the publication, use of, or reliance upon any IEEE Standard document.

IEEE does not warrant or represent the accuracy or content of the material contained in its standards, and expressly disclaims any express or implied warranty, including any implied warranty of merchantability or fitness for a specific purpose, or that the use of the material contained in its standards is free from patent infringement. IEEE Standards documents are supplied "AS IS."

The existence of an IEEE Standard does not imply that there are no other ways to produce, test, measure, purchase, market, or provide other goods and services related to the scope of the IEEE standard. Furthermore, the viewpoint expressed at the time a standard is approved and issued is subject to change brought about through developments in the state of the art and comments received from users of the standard. Every IEEE standard is subjected to review at least every ten years. If a document is more than ten years old and has not undergone a revision process, it is reasonable to conclude that its contents, although still of some value, do not wholly reflect the present state of the art. Users are cautioned to check to determine that they have the latest edition of any IEEE standard.

In publishing and making its standards available, IEEE is not suggesting or rendering professional or other services for, or on behalf of, any person or entity. Nor is IEEE undertaking to perform any duty owed by any other person or entity to another. Any person utilizing any IEEE Standards document, should rely upon his or her own independent judgment in the exercise of reasonable care in any given circumstances or, as appropriate, seek the advice of a competent professional in determining the appropriateness of a given IEEE standard.

Translations: The IEEE consensus development process involves the review of documents in English only. In the event that an IEEE standard is translated, only the English version published by IEEE should be considered the approved IEEE standard.

Official Statements: A statement, written or oral, that is not processed in accordance with the IEEE-SA Standards Board Operations Manual shall not be considered the official position of IEEE or any of its committees and shall not be considered to be, nor be relied upon as, a formal position of IEEE. At conferences, symposia, seminars, or educational courses, an individual presenting information on IEEE standards shall make clear that his or her views should be considered the personal views of that individual rather than the formal position of IEEE.

Comments on Standards: Comments for revision of IEEE Standards documents are welcome from any interested party, regardless of membership affiliation with IEEE. However, IEEE does not provide consulting information or advice pertaining to IEEE Standards documents. Suggestions for changes in documents should be in the form of a proposed change of text, together with appropriate supporting comments. Since IEEE standards represent a consensus of concerned interests, it is important to ensure that any response to comments and questions also receive the concurrence of a balance of interests. For this reason, IEEE and the members of its societies and Standards Coordinating Committees are not able to provide an instant response to comments or questions except in those cases where the matter has previously been addressed. Any person who would like to participate in evaluating comments or revisions to an IEEE standard is welcome to join the relevant IEEE working group at <http://standards.ieee.org/develop/wg/>.

Comments on standards should be submitted to the following address:

Secretary, IEEE-SA Standards Board
445 Hoes Lane
Piscataway, NJ 08854
USA

Photocopies: Authorization to photocopy portions of any individual standard for internal or personal use is granted by The Institute of Electrical and Electronics Engineers, Inc., provided that the appropriate fee is paid to Copyright Clearance Center. To arrange for payment of licensing fee, please contact Copyright Clearance Center, Customer Service, 222 Rosewood Drive, Danvers, MA 01923 USA; +1 978 750 8400. Permission to photocopy portions of any individual standard for educational classroom use can also be obtained through the Copyright Clearance Center.

Notice to users

Laws and regulations

Users of IEEE Standards documents should consult all applicable laws and regulations. Compliance with the provisions of any IEEE Standards document does not imply compliance to any applicable regulatory requirements. Implementers of the standard are responsible for observing or referring to the applicable regulatory requirements. IEEE does not, by the publication of its standards, intend to urge action that is not in compliance with applicable laws, and these documents may not be construed as doing so.

Copyrights

This document is copyrighted by the IEEE. It is made available for a wide variety of both public and private uses. These include both use, by reference, in laws and regulations, and use in private self-regulation, standardization, and the promotion of engineering practices and methods. By making this document available for use and adoption by public authorities and private users, the IEEE does not waive any rights in copyright to this document.

Updating of IEEE documents

Users of IEEE Standards documents should be aware that these documents may be superseded at any time by the issuance of new editions or may be amended from time to time through the issuance of amendments, corrigenda, or errata. An official IEEE document at any point in time consists of the current edition of the document together with any amendments, corrigenda, or errata then in effect. In order to determine whether a given document is the current edition and whether it has been amended through the issuance of amendments, corrigenda, or errata, visit the IEEE-SA Website at <http://standards.ieee.org/index.html> or contact the IEEE at the address listed previously. For more information about the IEEE Standards Association or the IEEE standards development process, visit IEEE-SA Website at <http://standards.ieee.org/index.html>.

Errata

Errata, if any, for this and all other standards can be accessed at the following URL: <http://standards.ieee.org/findstds/errata/index.html>. Users are encouraged to check this URL for errata periodically.

Patents

Attention is called to the possibility that implementation of this standard may require use of subject matter covered by patent rights. By publication of this standard, no position is taken by the IEEE with respect to the existence or validity of any patent rights in connection therewith. If a patent holder or patent applicant has filed a statement of assurance via an Accepted Letter of Assurance, then the statement is listed on the IEEE-SA Website at <http://standards.ieee.org/about/sasb/patcom/patents.html>. Letters of Assurance may indicate whether the Submitter is willing or unwilling to grant licenses under patent rights without compensation or under reasonable rates, with reasonable terms and conditions that are demonstrably free of any unfair discrimination to applicants desiring to obtain such licenses.

Essential Patent Claims may exist for which a Letter of Assurance has not been received. The IEEE is not responsible for identifying Essential Patent Claims for which a license may be required, for conducting inquiries into the legal validity or scope of Patents Claims, or determining whether any licensing terms or conditions provided in connection with submission of a Letter of Assurance, if any, or in any licensing agreements are reasonable or non-discriminatory. Users of this standard are expressly advised that determination of the validity of any patent rights, and the risk of infringement of such rights, is entirely their own responsibility. Further information may be obtained from the IEEE Standards Association.

Currently in preview, click buy full version

Participants

At the time this IEEE recommended practice was completed, the P1799 Working Group had the following membership:

Remi Tremblay, *Chair*
Claude Hudon, *Secretary*

David Agnew
Kevin Alewine
Raymond Bartnikas
Kevin Backer
Stefano Bomben
Andy Brown
Donald Campbell
William Chen
Doug Conley
Ian Culbert
Jeffrey Fenwick
Shawn Filliben
Nancy Frost
Paul Gaberson

Michel Gagné
Bal Gupta
Gary Heuston
Richard Huber
Marcelo Jacob
Aleksandra Jeremic
Aleksandr Khazanov
Amir Khosravi
Thomas Klamt
Inna Kremza
Laurent Lamarre
Gerhard Lemesch
Rimma Malamud
William McDermid
David McKinnon

Charles Millet
Glenn Mottershead
Beant Nindra
Sophie Noel
Ramtin Omranpour
Howard Penrose
Helene Provencher
Emad Sharifi
John Schmidt
Jeffrey Sheaffer
Reza Soltani
Gregory Stone
Chuck Wilson
Hugh Zhu

The following members of the individual balloting committee voted on this recommended practice. Balloters may have voted for approval, disapproval, or abstention.

Michael Adams
David Agnew
Martin Baur
Thomas Bishop
Stefano Bomben
Steven Brockschink
Chris Brooks
Donald Campbell
Weijen Chen
Ian Culbert
Matthew Davis
Ray Davis
Gary Donner
Gary Engmann
Jeffrey Fenwick
Jorge Fernandez Daher
Sudath Fernando
Rostyslaw Fiestek
Paul Gaberson
Michel Gagné

Randall Groves
Bal Gupta
Werner Hoeft
Claude Hudon
Innocent Kinnwa
Jiri Kuchisky
Cheng-ju Lam
Benjamin Lanz
William Lockley
Greg Luri
Rimma Malamud
William McBride
William McCown
William McDermid
David McKinnon
Don McLaren
James Michalec
G. Harold Miller
Charles Millet
Jerry Murphy

Arthur Neubauer
Michael S. Newman
William Newman
Sophie Noel
Lorraine Padden
Christopher Petrola
Alvaro Portillo
Iulian Profir
Bartien Sayogo
John Schmidt
Jeffrey Sheaffer
Gil Shultz
Reza Soltani
Gary Stoedter
Gregory Stone
James Timperley
Remi Tremblay
John Vergis
Kenneth White
Hugh Zhu

When the IEEE-SA Standards Board approved this recommended practice on 19 October 2012, it had the following membership:

Richard H. Hulett, *Chair*
John Kulick, *Vice Chair*
Robert M. Grow, *Past Chair*
Konstantinos Karachalios, *Secretary*

Satish Aggarwal
Masayuki Ariyoshi
Peter Balma
William Bartley
Ted Burse
Clint Chaplin
Wael Diab
Jean-Philippe Faure

Alexander Gelman
Paul Houzé
Jim Hughes
Young Kyun Kim
Joseph L. Koepfinger*
John Kulick
David J. Law
Thomas Lee
Hung Ling

Oleg Logvinov
Ted Olsen
Gary Robinson
Jon Walter Rosdahl
Mike Seavey
Yatin Trivedi
Phil Winston
Yu Yuan

*Member Emeritus

Also included are the following nonvoting IEEE-SA Standards Board liaisons:

Richard DeBlasio, *DOE Representative*
Michael Janezic, *NIST Representative*

Julie Alessi
IEEE Standards Program Manager, Document Development

Malia Zammit
IEEE Standards Program Manager, Technical Program Development

Introduction

This introduction is not part of IEEE Std 1799-2012, IEEE Recommended Practice for Quality Control Testing of External Discharges on Stator Coils, Bars, and Windings.

External discharges in the end-windings are caused by inadequate workmanship for globally vacuum-pressure impregnated (VPI) stators or problems on stators assembled on-site. Poorly finished lashes with an insufficient gap between bars produces coil-to-coil or bar-to-bar discharges. Misalignment between adjacent coils or bars may also reduce the gap distance and generate a high electric stress larger than the air breakdown strength. Sometimes misplaced resistance temperature detector (RTD) or air gap monitor leads have been seen to cause partial discharges (PDs) with high-voltage bars or coils. External discharges for the individual coil/bar could also be a result of improper design, improper material, or improper workmanship. After many years, the deterioration induces surface degradation that may lead, in the long run, to a phase-to-ground fault and reduce the overall reliability of the system. More detail on the theory of external discharges and their effects is given in Annex A. Some utilities have seen deterioration of the junction between the stress control coating and semiconducting slot coating of stator windings after only a few years of operation. Other secondary effects, such as the production of a large quantity of ozone, which may be deleterious to the equipment and dangerous to personnel, is also of concern. In addition, over the years, the ground-wall insulation thickness of stator coils and bars has been reduced to improve heat transfer through the ground-wall insulation. This optimization does, however, increase the dielectric stress on the insulation and on the end-winding stress grading system making them more susceptible to developing electrical discharges.

In the current recommended practice, the term “semiconducting slot coating” is preferred to “semiconductive slot coating” often used in the industry. These coatings, composed of resin, varnish, enamels, or other compounds, are filled with carbon black powder, graphite, or other filler and should have electrical resistivity per unit of surface of $1 \times 10^2 - 5 \times 10^5$ ohms per square. The semiconducting slot coating applied on the insulation surface of the slot parts of winding must have uniform tight contacts with the grounded walls of the stator slot. This coating provides minimum voltage between the surface of the coil or bar and the grounded stator core.

A stress control coating must be applied on all end turns of high-voltage stator winding and overlap the semiconducting slot coating to provide electrical contact between them. The stress control coating has a non-linear resistance with voltage.

This recommended practice presents two methods for evaluating the quality of materials and design, factory workmanship, and on-site workmanship. The first one, the blackout test, has been used for many years. The second one, the corona-imaging inspection, is more recent and presents several advantages. Each method has its advantages and disadvantages.

IEEE Std 1434 mentions these two inspection methods but with very little detail. The current recommended practice includes a more elaborate description of sample preparation, bench tests, test conditions, and acceptance criteria in the factory and on-site.

Contents

1. Overview	1
1.1 Scope	2
1.2 Purpose	2
2. Normative references.....	2
3. Definitions	3
4. Test preparation and safety.....	5
5. Test equipment and connections.....	5
5.1 Sensitivity of the corona-imaging instruments	6
6. Quality control test of external discharges with corona-imaging instrument or blackout test.....	7
6.1 Factory test on coils and bars.....	8
6.2 Stator model test.....	10
6.3 Test on fully assembled stator windings.....	14
7. Data records.....	20
7.1 How to fill the data logging tables.....	20
Annex A (informative) Theory of optical emissions from external discharges.....	24
Annex B (informative) Variability of discharge inception and extinction voltages	27
Annex C (informative) Example of determination of the maximum voltage for a specific winding diagram.....	28
Annex D (informative) Example of correction factor to apply to the test voltage of a stator model and VPI stator for a machine which will operate at altitudes of more than 1000 m.....	31
Annex E (informative) Example of operating-voltage table and bar/coil identification table used during test.....	33
Annex F (informative) Bibliography	35

IEEE Recommended Practice for Quality Control Testing of External Discharges on Stator Coils, Bars, and Windings

IMPORTANT NOTICE: IEEE Standards documents are not intended to ensure safety, health, or environmental protection, or ensure against interference with or from other devices or networks. Implementers of IEEE Standards documents are responsible for determining and complying with all appropriate safety, security, environmental, health, and interference protection practices and all applicable laws and regulations.

This IEEE document is made available for use subject to important notices and legal disclaimers. These notices and disclaimers appear in all publications containing this document and may be found under the heading “Important Notice” or “Important Notices and Disclaimers Concerning IEEE Documents.” They can also be obtained on request from IEEE or viewed at <http://standards.ieee.org/IPR/disclaimers.html>.

1. Overview

This quality control test is used to confirm that the insulation system of the stator winding of generator and motor operating in air, including the semiconducting slot and stress control coatings, are free of external discharges. Quality control of the semiconducting slot coating, stress control coating, and manufacturing process is best done in the factory. For stators assembled on-site, such as those for large hydro-generators, additional tests can be performed on the fully assembled generator in order to control the quality of the assembly and workmanship. This control includes:

- a) evaluation of the spacing between end-arms and with the phase circuit rings or connections to the main phase terminals
- b) confirming proper alignment of the ground plane made by the semiconducting slot coating on the straight portion of the bar/coil with regard to the core pressure finger
- c) the positioning of all cables (RTD, air gap monitor) with respect to high voltage and
- d) inspection of imperfections that may have been introduced during assembly (presence of foreign objects, misplaced slot center filler, chips and scratches to bars or coils coating)

In the case of machines assembled in the factory, such as VPI machines, the complete quality control test can be done in the factory. However, special care should be taken so that no change in the machine's

conditions occur during transportation (contamination by water and dust, or damage to end-arms during movement). The use of this recommended practice may eliminate the need for users to specify minimum clearances between bars/coils in the end-winding to avoid surface discharge activity.

1.1 Scope

This recommended practice provides a procedure to detect external discharges in form-wound bars and coils and complete stator windings of rotating machines operating in air with a rated line-to-line voltage greater than 4200 V at power frequency. The recommended practice is applicable to bars, coils, and complete stator windings. The recommended practice covers two inspection methods: the visual blackout test, and the use of corona imaging instruments.

1.2 Purpose

The purpose of this recommended practice is to suggest specimen preparation, test parameters, and procedures for detecting external discharges associated with bars, coils, and complete stator windings using the above mentioned methods. It also recommends acceptance criteria and a procedure for retest in the event of a test failure.

2. Normative references

The following referenced documents are indispensable for the application of this document (i.e., they must be understood and used, so each referenced document is cited in text and its relationship to this document is explained). For dated references, only the edition cited applies. For undated references, the latest edition of the referenced document (including any amendments or corrigenda) applies.

IEC 60204-1, Safety of machinery—Electrical equipment of machines—Part 1: General requirements.

IEC 61508, Functional safety of electrical/electronic/programmable electronic safety-related systems.

IEEE Std 4, IEEE Standard Techniques for High-Voltage Testing.^{1, 2}

IEEE Std 4a, Amendment to IEEE Standard Techniques for High-Voltage Testing.

IEEE Std 510-1983 (Withdrawn), Recommended Practice for Safety in High-Voltage and High-Power Testing.³

ISO 14121-1, Safety of Machinery—Risk Assessment—Part 1: Principles.

ISO/TR 14121-2, Safety of Machinery—Risk Assessment—Part 2: Practical Guidance and Examples of Methods 2.

¹ The IEEE standards or products referred to in this clause are trademarks of The Institute of Electrical and Electronics Engineers, Inc.

² IEEE publications are available from The Institute of Electrical and Electronics Engineers, 445 Hoes Lane, Piscataway, NJ 08854, USA (<http://standards.ieee.org/>).

³ IEEE Std 510-1983 has been withdrawn; however, copies can be obtained from The Institute of Electrical and Electronics Engineers, 445 Hoes Lane, Piscataway, NJ 08854, USA (<http://standards.ieee.org/>).